

INSTALLATION INSTRUCTIONS FOR DETECTO PORTABLE WHEELCHAIR AND STRETCHER SCALE RAMPS

UNPACKING

Before starting to assemble, please unpack and remove all wrappings and fillers. Carton contains:

Item Description	Part Number	Qty.
6400, 6500, 6550, 6560, and 6570 Ramp Weldment	0065-0675-0A	2
6600 and BRW1000 Ramp Weldment	0065-0731-0A	2
8500 and 8550 Ramp Weldment	0065-0821-0A	2
.25-20 X .438" Flat-Head Socket Cap Screw Zinc Plated	6021-1812	4
5/32" Short Hex Key	M220-0080-00	1
0.5 ml Packet High Strength Thread Locker	6560-1046	1

ASSEMBLY

Refer to Figures No. 1, 2, and 3, then follow the instructions for attaching the ramps.

NOTE: On the 6550, 6560, 6570, and 8550, ensure the column(s) are locked onto scale platform.

- 1. Lift scale and place the platform on its side in the transport position. Have an assistant hold the platform while installing the ramps.
- 2. Attach each ramp in the following sequence:
 - Begin with top rubber mount. Apply thread locker to first screw. Then, while holding ramp against top rubber mount, hand thread screw into top rubber mount (Figure No. 1).
 - Next, apply thread locker to second screw, and while holding ramp against bottom rubber mount, hand thread screw into bottom rubber mount.
 - Tighten both screws with supplied 5/32" Short Hex Key (Figure No. 2).

NOTE: When installing screws into rubber mount, be careful not to over-tighten.

3. Repeat Step 2 for ramp on other side of platform. Finished assembly should look like Figure No. 3.



Figure No. 1





Figure No. 3



Figure No. 2